

X-Loupe® Solution

Portable Microscope Camera

User Manual

The contents of this document may not be copied nor duplicated in any form, in whole or in part, without prior written consent from Lumos. Lumos makes no warranties as to the accuracy of the information contained in this document or its suitability for any purpose. The information in this document is subject to change without notice.

Copyright © 2010 Lumos. All rights reserved

Preface

Thanks on behalf of the Lumos team for using Image Management Software -X-Loupe Solution.

Lumos wants to carry out its service and, with this preface, provide an introduction to the user manual, so that everyone can gain the fullest possible advantage of it.

The graphical user interface (GUI), is modernized to the new de facto 'Office 2007' GUI. It has a very logical grouping of functionality – in most cases you will find the functionality where you expect to find it. The dock bars can be rearranged or hidden after individual needs.

The software package is multilingual, it includes the following languages: English, Japanese, Traditional Chinese, and Korean. The language can be switched on-the-fly – no need to install special packages to have your language.

Table of Contents

Preface *2*

1. Start Installations *3*

2. X-Loupe Solution - Image Management Software *4*

2.1 Initial View **4**

2.2 Dock Bars **5**

2.3 Image Gallery **6**

2.4 Panorama View **6**

3. Calibration *7*

3.1 Edit Optics Configuration **7**

3.2 Calibrate an objective lens **8**

3.3 Backup/ Restore Configuration, Import/Export Device **9**

3.4 Import Factory Calibration Data **10**

4. Menu Bar *11*

4.1 Home **11**

4.1.1 Realize 11

4.1.2 Excel Report 12

4.1.3 PDF Report 13

4.2 View **14**

4.3 Measurement and Annotation **14**

4.3.1 Annotation 14

4.3.2 Measurement 15

4.3.3 Save the Annotations and Measurements 15

4.4 Still Image **16**

4.5 Image Extender **16**

4.5.1 Extended Focus 16

4.5.2 Extended Exposure 17

1. Start Installations

If you have problems installing or using the software, you can e-mail our technical support group at service@lumos.com.tw or you can contact your local dealer or distributor to get further direct support.

Please also visit our homepage at www.x-loupe.com for software updates or other improvements for your X-Loupe.

Sequence to install X-Loupe Solution

A. Detach any X-Loupe dongle from your PC

B. Install the new software package from your CD or from www.x-loupe.com.

C. Attach dongle (Note: X-Loupe Solution requires a dongle to run). If it is the first time the dongle is attached you should see a 'Found new Hardware' sequence. Wait for the sequence to complete. Later dongle attachments will issue the Windows 'ding-dong' sound

D. Start X-Loupe Solution software.

Dongle Check

To check that the dongle is properly installed, see the device manager, where the USB Dongle icon should appear.



2. X-Loupe Solution - Image Management Software

X-Loupe Solution is an image handling software allowing advanced functions for zooming, annotation, measurements, and locating and maintaining images. The software can create online image galleries with image browsing capabilities.

The main features of the software are Thumbnails, Multiple views, Annotation, Measurement, Active Zoom, Extended Exposure, Extended Focus, and Reporting (Excel and PDF).

2.1 Initial View

After the program has been installed, your screen should look like this:



At the top of the window, you will see the **Quick Access Toolbar**. The Quick Access Toolbar in the live preview:

Select **System Maintenance** in the X-Loupe logo menu. It is allowed to select **Language and Color** to set the language as another language:



2.2 Dock Bars

The program uses the concept of document docking. It allows the dock bars to be hidden or shown in fixed locations

Hide the dock bar by clicking the 'pin':



To view, move the cursor to the fane:



Show the dock bar by clicking the 'pin':



It is also possible to move and rearrange the dock bars to desired locations in the GUI.

Move a dock bar on top of another dock bar by dragging the dock bar, and place it on the top spot of the cross:



Move to left:



Move to bottom:



Move to right:



2.3 Image Gallery

There are two Image Galleries in X-Loupe Solution dock bars. Click **Change Directory** to browse the thumbnail images of specified directory. The images will be displayed ordered by file name. Thumbnail size can be Small, Medium, or Large.

Select one thumbnail image and click **Open** button to view the whole image.

2.4 Panorama View

The **Panorama View** dock bar can display a view of the main image at a smaller magnification and a rectangle indicating the size and position of the visible portion of the image. The blue rectangle can be dragged around in **Panorama View** with the left mouse button to pan or move the image.



3. Calibration

It is important to calibrate your cameras and optics before using them for measurements. Using the program without correct calibrations will result in incorrect calculations and measurements

3.1 Edit Optics Configuration

Select **System Maintenance** in the X-Loupe logo menu. Then select **Edit Optics Configuration:**



Right-click on **Optics Configuration** to **name** this system, then select **Add:**



Right-click on the new **system name** to **name** the objective lens in use, then select **Add**:



Click **Save Configuration** button, then close the dialog box.

3.2 Calibrate an objective lens

Images acquired with a wrong calibration setting can be recalibrated. The calibration data can apply to other images taken by the same objective lens.

To calibrate an objective lens:

Firstly, take a photo with a reference ruler and open the photo with the software. Select the correct **Optics device** and **Magnification** from **Device Select** dock bars. Click **Calibrate** and select **Draw calibration ruler for calibration** to draw ruler on a known reference.



Or use **Ruler** from Measurement tools to draw a ruler on a known reference. The measurement may show an incorrect value.



Click on **Calibrate**, then insert the **true length** of the ruler in empty space and choose the right **unit**:



Then select **Calibrate this optics objective lens** to finish this calibration process:



★ We recommend to calibrate every device manually.

★ For other images, select the same device (**Optics device**) and objective lens (**Magnification**) to apply the calibration data.

★ Lumos provides factory-setting calibration data for each X-Loupe series and models. Please visit our webpage www.x-loupe.com to download the calibration files and import the calibration data using **Import Device** function.

3.3 Backup/ Restore Configuration, Import/Export Device

To backup the calibration data of whole configuration, please select **Backup Configuration** and input backup filename on the pop-up dialog box.



To restore the calibration data of whole configuration, please select **Restore Configuration** and input previous backup filename on the pop-up dialog box.

★ Please note that all calibration and configuration data will be overwritten after the restoring process.



For one specific device, select **Export Device** to export calibration data of all its objective lenses. Input the filename in the pop-up dialog box to save the export file.



To import the whole calibration data of one specific device, please select **Import Device** and input previous export filename in the pop-up dialog box.

There will be a serial number attached if the device name is duplicated.



3.4 Import Factory Calibration Data

Lumos provides factory-setting calibration data for all X-Loupe series and models. Please visit our webpage www.x-loupe.com to download the calibration files and import the calibration data using **Import Device** function.



4. Menu Bar

The Menu bar is also called a rubber bar, which is designed to automatically fit any screen size. On the Menu Bar, there are five fanes with different functions, which are grouped under the relevant topics.



4.1 Home



4.1.1 Realize

Realize makes the annotation a part of the image. This is good e.g. when sending an image to a person without access to X-Loupe Solution Software.

Select **Realize** to write the annotation and measurement into the image itself. It is not possible to modify those annotation and measurement after realizing.

4.1.2 Excel Report

When the measurements and annotation are done, it is possible to export the data to an Excel document.

Before generating the report, select an Excel report template.

The report template is located in the application data folder (C:\Documents and Settings\%USERNAME% \Application Data\Lumos Technology). It is possible to make some modifications on the template report, like changing the logo, header etc. DO NOT change the word with %, e.g. %DATE%.

Select **Excel report** to generate an Excel document. The document will be automatically opened after generation if the **Open report** option is checked.



The illustration to the right is the final report with logo, header, date and time, data and image. It is possible to make some modifications on the report, like adding comments, changing the logo, etc.



4.1.3 PDF Report

When the measurements and annotation are done, it is also possible to export the data to a PDF document.

Select **PDF report** to generate a report with PDF format.

One temporary Excel report will be generated based on the report template. The PDF report is generated by converting that Excel report to PDF format.

It is also possible to convert an existing Excel report to a PDF report by selecting **Excel to PDF.**

The illustration to the right is the final PDF report with logo, header, date and time, data and image.

4.2 View



4.3 Measurement and Annotation



4.3.1 Annotation

Annotations are notations added to the captured image. Choose a type of annotation in the **Measuring** menu, then draw on the image:

Use the formatting tools from **Home** to change font/line size and color.



4.3.2 Measurement

X-Loupe Solution has many measuring functions: ruler, ellipse, protractor, three point circle, circle center distance, point to line distance etc.

To measure a(n); angle, distance, area…
Choose the tool, then draw on the image:

The calculated results will automatically show next to the drawing. Use the formatting tools from Home to make font/line adjustments as desired.



4.3.3 Save the Annotations and Measurements

Here are two ways of saving the annotations and measurements:

One way is to click on the disk button, and the annotations and measurements will be saved in a separate file:

The annotations and measurements belonging to the image will appear automatically by using X-Loupe Solution to open this image, and editing is possible. The other image viewer will only show the original image without the annotations and measurements.

Another way is to save the image and the annotations and measurements in one file:

The program will burn the annotations and measurements on the original image, so a new image is created. In this way the annotations and measurements will no longer be editable.

4.4 Still Image

In the Still Image menu there are several adjustment tools available for changing the specifications of a captured image.



4.5 Image Extender

Image Extender is only available in X-Loupe Solution Premium. The **Extended focus** and **Extended exposure** functions can create an image, where multiple depths and multiple exposures are all in focus at once, by putting the different layers together to one image.

4.5.1 Extended Focus

Microscopy imaging often suffers from limited depth-of-focus. However, the object can be “optically sectioned” by moving the object along the optical axis; different areas appear in focus in different images. Extended focus function in X-Loupe Solution, can combine those images into one single sharp image. If the images have different angles to the optical axis, as is the case with stereo microscopes, the software will automatically compensate for this.

The combination of the extended focus capability in X-Loupe Solution and the extremely high resolution capability of the X-Loupe makes it easy to capture stunningly high quality images with almost unlimited focus depth, ideal for research and routine work.

Example:

Capture several images from top to bottom at the different focus levels (increase or decrease

focus with as similar intervals as possible). For example, if the object of interest has a depth of 1mm and the depth of focus of the optics of the microscope is 0.25mm, four images must be captured.



Then select **Execute**, and wait.

Source Images:



Extended focus image:



★ Please note that only images with the object of interest must be open. Other images of different objects must be closed.

★ Please note that the output image will not be ready immediately, as the extended focus calculation takes some time.

4.5.2 Extended Exposure

Extended Exposure combines multiple images, each captured with different exposure time

and having only a part of the image correctly exposed. This is very useful when the object under inspection has reflections, very dark or very bright areas in combination, thereby making it impossible to expose the total image correctly with one single capture. X-Loupe Solution can combine these images into one single well-exposed image.



Then select **Execute**, and wait.

Taking photo of fingerprints on a surface with high reflection and very dark or very bright areas in combination.



Extended exposure image:

★ Please note that only images with the object of interest must be open. Other images of different objects must be closed.

★ Please note that the output image will not be ready immediately, as the extended exposure calculation takes some time.